

iT32 固件说明

- 一、请使用神牛固件升级软件 G3 V1.1 及以上版本打开该固件进行升级，G3 可在官网下载。
- 二、版本号查看方法：开机后，进入菜单界面，在最后面找到设备信息，可以看到软件版本号（如 1.00 版本：V1.00）。
- 三、iT32 升级方法：方法 1.开机后，进入菜单，找到设备信息，用 USB 线连接电脑后，点击固件升级。方法 2.关机状态按住 SET 按键，再插入 USB 接口连接电脑进入升级。
- 四、X5 升级方法：iT32 关机状态下，将 X5 组装到 iT32 上，然后长按 iT32 的电源键开机，如果 X5 不是最新版本则会自动进行升级。
- 五、版本说明：

版本	更新内容	日期
V1.10	1. 修复 X5C 在一些佳能相机上无线引闪从属灯会过曝的问题，这些相机为支持光无线的相机。 2. 修复 X5S 唤醒后有概率无法控制从属灯的问题。 3. 修复 X5O 在相机关机状态下无法睡眠的问题。	25/11/17

注：详细规格请在官网（www.godox.com.cn）下载最新说明书。

iT32 Firmware Release Note

1. Please use Godox firmware upgrade software G3 V1.1 or later to open this firmware file to proceed with the upgrade. G3 can be downloaded on the official website.
2. How to check the version number:After the device is powered on, go to the menu page and find the device information at the very end. You can see the software version number (e.g. Version 1.00: V1.00).
3. iT32 upgrade instructions: Method 1.After powering on the device, enter the menu, find the device information, connect the computer via a USB cable, and then click on firmware upgrade. Method 2.In the powered-off state, press and hold the SET button, then insert the USB interface to connect to the computer and proceed with the upgrade.
4. X5 upgrade instructions: Mount X5 on the powered-off iT32, press and hold the power switch button of iT32 to turn it on, X5 will automatically upgrade if it's not the latest version.
5. Version Instructions:

Version	What's New	Date
V1.10	1. Fixed an issue where the X5C's wireless triggering receiver flash would overexpose on certain Canon cameras that support optical wireless. 2. Fixed an issue where the X5S occasionally failed to control the receiver flash after waking up. 3. Fixed an issue where the X5O failed to enter sleep mode	25/11/17

	when the camera was powered off.	
--	----------------------------------	--

Note: For more details, please download the newest instruction manual on the official website:
www.godox.com.